

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DEL,
3-CLAVI.V,
1-

Blackwater Presbyterian Church
State Road 54
Clarksville vicinity
Sussex County
Delaware

DE-200

Documentation: 8 exterior photos (1982)
2 interior photos (1982)
1 data page (1983)

Jack E. Boucher, Photographer July, 1982

DE-200-1 SOUTH FRONT FROM SOUTHWEST

DE-200-2 SOUTH FRONT

DE-200-3 SOUTH FRONT FROM SOUTHEAST

DE-200-4 SOUTH FRONT FROM SOUTHEAST, CLOSER

DE-200-5 SOUTH FRONT FROM EAST

DE-200-6 EAST SIDE

DE-200-7 SOUTH FRONT, DETAIL OF DOORWAY

DE-200-8 WEST SIDE, DETAIL OF WINDOW

DE-200-9 INTERIOR, LOOKING NORTH

DE-200-10 INTERIOR, LOOKING SOUTH

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DEL,
3-CLAVI.V.,
1-

ADDENDUM TO:
BLACKWATER PRESBYTERIAN CHURCH
State Road 54
Clarksville Vicinity
Sussex County
Delaware

HABS No. DE-200

DE-200-1 through DE-200-10 were transmitted the Library of Congress in 1983.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, July 1982

DE-200-11 (CT)	SOUTH FRONT FROM THE SOUTHWEST
DE-200-12 (CT)	SOUTH FRONT FROM THE SOUTHEAST
DE-200-13 (CT)	SOUTH FRONT, DETAIL OF DOORWAY